



Newsletter Index

Index by Subject Matter

150x150

150x150 Heart Centre - November 2011

150x150 Repeated Warning - March 2013

3D Printing

Seminar on Direct Manufacturing Through 3D printing - January 2013

3D (additive manufacturing) Seminar review - February 2013

Barbecue Tables

New Barbecue Table (Flinders)- March 2012

AutoCAD Block for Flinders Table - April 2012

Robust Barbecue Tables - December 2013

Boardwalks – refer also to projects

Boardwalks and fire- June 2011

Books

A Reference from Someone who Knows - March 2013

Publications by Ted Stubbersfield - November 2012

Construction Timbers in Queensland - December 2012

Horse Fencing - December 2013

Timber Preservation Guide Finished - January 2013 and February 2013

Le Memento du Forestier - January 2013

Le Memento du Forestier update - February 2013

Book on Timber Grading is progressing - September 2013

Guide to Grading Hardwood - September 2013

An unsolicited comment on Hardwood Grading Book - November 2013

Bollards

200x100 or 200x75 bollards? - September 2012

Eclipse bollards in stock - September 2011

Turned Bollards - June 2012

Stainless Steel Bollards - May 2013

Bridges

Arched footbridges - May 2010

Do footbridges have to be minimalist? - April 2012

Dutch and Footbridges - April 2012
First Somerset Bridge - August 2012
Heritage Lattice Truss - March 2012
Bridge Inspection Course level 1 and 2 - March 2012
Bridge Inspection Course Level 1 Report - December 2012
Long span bridges - October 2011
Mathematical Bridge - April 2012
Nailplates in Bridges - May 2010
New Designs coming - August 2010
Segmented Bridge - April 2012
Small Bridge Conference - May 2011
Swale Drain Bridges - August 2013
Timber Bridge Refurbishment - August 2011
Very Long Span Bridges - July 2012
Vibration and load requirements - May 2010

Brochures

First Brochure of Three New Bridges - September 2010
Segmented Bridges - October 2010
Somerset Bridges - October 2010
Japanese bridge Brochure - January 2011

Case Histories

Deckwood Helps Win Yet Another Award - November 2012
Lessons from a Failed Boardwalk - April 2013
Noah's Ark in Hong Kong - January 2011
Specifications Should Mean Something - March 2012
Unsuitable Decking - September 2013
New Life for an Old Timber Bridge - September 2013
Earthcentre, Doncaster, South Yorkshire - November 2013
House of the Five Senses, The Netherlands - November 2013
Service Station, South Africa - November 2013
National Park, Kenya - November 2013
Market Assessment and Evaluation November 2013

Consultancy Services by Ted Stubbersfield - July 2012, and February 2013

Dampcourses

Malthoid a Mixed Blessing – September 2011

Decking

Avoid long points on decking - January 2012
Avoid Substitution - February 2013
Be Careful when you Specify Deckwood - November 2012
Be Very Careful With Substitutes - January 2013

Decking and Gardens - July 2012
Domestic Decking on Steel Joists - June 2012
Do Not Play With the Deckwood(TM) Specification – March 2013
Gaps - January 2011
Gaps and Solicitors August 2011
Gaps and Solicitors – extra September 2011
Gaps – a reminder March 2012
Laying on concrete with small clearance - February 2011
Use the right product when building a deck - December 2012
UV is Higher in the Southern Hemisphere - February 2013
Plastic Decking - May 2011
Plastic Decking Discussion Forum - March 2013 Special Edition
Boardwalks and fire - June 2011

Deck Collapses

Deck Collapses - February 2010
Coroner's Report Released on Deck Fatality at Yeppoon – October 2012
Yet another Deck Collapse - March 2013

Decking Oil

Oils Aint Oils - September 2012
Sealing CCA Treated Timber - September 2012

Design

Safety Must Take Precedence over Beauty - May 2013
Why has timber got such a bad name? - June 2013
Can I Help A Damsel in Distress? - June 2013
Why is Timber Use/Supply Deteriorating? - September 2013
You wouldn't do it with Steel - December 2013
Timberlife prediction software - August 2010
Theory Must Match Performance - August 2011
Timber Design is Dead - October 2012

Defects in Timber

Identify and Assess That Defect - May 2012
Durability April 2010, - July 2010,

F14, F17

Deckwood is not F17 - July 2012
Do Not Play With the Deckwood(TM) Specification - March 2013
F17 and F11 KD Hardwood Specification - November 2011
Identify and Assess That Defect - May 2012
Identify and Assess That Defect postscript - June 2012
F17 is an Almost Useless Specification- January 2013

Fasteners

Bolt Edge Clearances - August 2011

Man O War Nuts, a Useful Piece of Hardware - October 2011

Reader Feedback on volute washers - March 2011

Volute washers a Useful Piece of Hardware - February 2011

Gaps

Gaps - January 2011

Gaps and Solicitors - August 2011

Gaps and Solicitors - extra September 2011

Gaps - a reminder March 2012

Grantham

Grantham Beautification - August 2012

Grantham Community Centre Completed - August 2013

New Definition of 1 in 100 Flood - February 2013

Post Flood Redevelopment at Grantham - January 2012

Rotary seeks donations for Grantham Flood Reconstruction - January 2013

Update on Redevelopment - October 2011

Handrail

Avoid substitution - August 2010

Correct Use of LOSP Treated Handrail - February 2012

Custom Handrail for Historical Home - July 2012

Handrail Height with Horses - February 2012

New design tools for C4 rail - November 2010

Specifying Timber Handrail - November 2011

Heart Centre timber

Forgive Me Father for I have Sinned - September 2012

Joists

Domestic Decking on Steel Joists - June 2012

Fibre Composite Joists November - 2012

Kwila/Merbau

Take care when specifying - August 2010

Merbau - see Kwila

Patent Approved September 2010

Plastic Decking – see Decking

Boardwalks and fire - June 2011

Posts

Installing in concrete - March 2011

Installing in supports - April 2011

A Reminder about Concrete and Hardwood Posts - July 2012

Pioneer Post Tames a 200x200 - November 2013

Post Spacing and how it Relates to Wire Tension - December 2013

Presentations August 2010

Preservatives

A Reminder of Why You Treat – May 2013

When is a preservative not a preservative - January 2010

Timber treatment 101 part 1 - November 2010

Timber Treatment 101 part 2 - December 2010

Why You Cannot “Preserve” Sawn Hardwood - July 2013

Projects

A Job I Could Have Done Better - December 2011

A Job I Could Not Have Done Much Better - December 2011

Bikeway Deck and Boardwalk at Thornlands - October 2010

Boardwalk at Mt Coot-tha - October 2012

Boardwalk Don Lucas Reserve Upgrade - May 2012

Boardwalk Don Lucas Reserve Upgrade postscript - June 2012

Boardwalk Fleay’s Wildlife Park - September 2011

Boardwalk in High Moisture Environment - January 2012

Boardwalk Riverstone Rise, Boyne Island Rd, Boyne Island - August 2013

Boardwalk Tannum Blue Boardwalk and Deck - December 2013

Boardwalk This has to be Ted’s Decking! - October 2013

Boardwalk Wearing Park- September 2011

Bridge at Everton Hills - October 2010

Bridges at Fitzgibbon - October 2010

Good Sounding Timber - June 2011

Grantham Post Flood Redevelopment - January 2012

Grantham Beautification - August 2012

Gympie RC All abilities Playground - June 2011

Observation Deck Ipswich - October 2010

Thursday Island Foreshore - February 2011

Walkway - Richlands Railway Station - June 2011

Recycled Timber

Recycled verses Pioneer Posts - October 2010

Specifications for Recycled Timber - July 2011

Resource

Design for the resource available - September 2010

What will we do with our Hardwood Plantations? - November 2013

Seasoning

60 Year Old Timber Still Unseasoned - December 2013

Shelter sheds

Large Playground Shelters - February 2012

New designs - January 2010

Octagonal Shelter - March 2012

Revision to Shelter Sheds - July 2011

Shelter Sheds in Natural Disasters - August 2011

Update on 14m Octagonal Shelter - March 2012

Sleepers

Sleepers in landscaping - August 2012

A Product Opportunity Identified, The "Sleep Easy" Sleeper - July 2013

The "Sleep Easy" Sleeper feedback - August 2013

Small Diameter timber

What will we do with our Hardwood Plantations? - November 2013

Earthcentre, Doncaster, South Yorkshire - November 2013

House of the Five Senses, The Netherlands - November 2013

Service Station, South Africa - November 2013

OI Tukai Lodge. Amboselli National Park, Kenya - November 2013

Market Assessment and Evaluation - November 2013

Species

What Species is That? - December 2011

Warning about Pacific Tallowood - September 2013

Sundry

Fabrication Services used by OSA and Infrastrucion - August 2012

Local Blacksmith Artist - February 2012

Routed Signage - May 2013

Specifying Sandstone - August 2012

What will we do with our Hardwood Plantations? - November 2013

Tanacoat

Update to Tanacoat Colours - October 2010

Tanacoat and UV - March 2013

Timber Design – see Design

Tannin Stains

Merbau/Kwila - August 2010

Feedback from readers - September 2010

Volute Washers

A useful item of hardware - February 2011

Reader Feedback on volute washers - March 2011

Timber Sizes - March 2010

Timber utilisation Acts

Queensland Act repealed - February 2011

Wire Balustrade

Simplifying wire balustrade - June 2010

Post Spacing and how it Relates to Wire Tension - December 2013

Ted Stubbersfield

Timber Design Assistant

Version 1.0 December 2013

OUTDOOR STRUCTURES

E-Mail: ted@outdoorstructures.com.au

Web: www.outdoorstructures.com.au

Phone: (07) 5462 4255

Fax (07) 5462 4077

Old College Road Gatton, Australia

PO Box 517 Gatton Q 4343

Australia

ABN 29 713 463 351

